









Mounting instruction

AIRCELL®5

BNC-Connector, screwable / Art. No. 7720

 <p>1. Cut off cable tail right-angled.</p>	 <p>5. Move the contact jacket as far as it will go between the copper braid and the foil. Cut off the copper braid with a side cutter. Remove 6 mm of the copper foil, then remove 5 mm of the dielectric with a side cutter.</p>
 <p>2. Move the nut, clamping ring and rubber washer over the cable head.</p>	 <p>6. Cut off the copper braid with a side cutter and move the rubber washer upfront to the contact jacket, so the rest of the copper braid is clamped between the rubber washer and the contact jacket.</p>
 <p>3. Remove 7 mm of the outer sheathing with a knife.</p>	 <p>7. Put the head pin onto the inner conductor and solder it. There should be a space of 1 mm between the inner pin and the copper foil.</p>
 <p>4. Bend copper braid upwards right angled.</p>	 <p>8. Insert the prepared cable head into the connector housing as far as it will go. Tighten the clamping nut with two jaw-wrenches of 11 mm hand-tight.</p>

Maahantuonti ja myynti:

PARATRONIC OY

Heikkiläntie 26, 63130 MÄYRY
 Puh 0400 297526 paratronic@paratronic.fi
paratronic.fi